



LuK Service Info



TB2031

Part Nr: 128 0055 11 — 280mm DBVR

Manufacturer: CASE-IH, MANITOU AND VOLVO

Art.-Nr.: 128 0055 11



628 1032 07 = 128 0055 11 + 328 0175 42 + 500 1046 50 + 410 0026 41
628 1032 09 = 128 0055 11 + 328 0175 42
628 1033 07 = 128 0055 11 + 328 0175 41 + 500 1046 50 + 410 0026 41
628 1033 09 = 128 0055 11 + 328 0175 41
628 2592 07 = 128 0055 11 + 328 0175 10 + 500 1046 50 + 410 0026 41
628 2592 09 = 128 0055 11 + 328 0175 10
628 2592 10 = 128 0055 11 + 328 0181 10 + 500 1046 50 + 410 0026 41

 Please ensure that the flywheel is machined to a pot depth of 36.6mm.


 Asegúrese de que el volante está mecanizado hasta una profundidad de 36.6mm.

 Das Schwungrad ist auf eine Tiefe von 36.6mm auszdrehen, siehe unten.

 Controllare che il volano venga rettificato a una profondità di 36.6mm.

 Veuillez vous assurer que le volant-moteur est rectifié à une profondeur de 36.6mm.

Flywheel
 Schwungrad
 Volant-moteur
 Volante-motor
 Volano



Call : +44 (0) 1432 264264
 vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT



Thrust pad 434 0342 10 is only required for release system already fitted with a thrust pad.



Druckstück 434 0342 10 ist nur erforderlich, wenn das Ausrücksystem bereits mit Druckstück ausgerüstet ist.



VL a bague d'appui 434 0342 10 n'est nécessaire que si la commande d'embrayage est déjà équipée d'une bague d'appui



La pieza de empuje 434 0342 10 solo es necesaria si el sistema de liberación ya está equipado con una pieza de empuje.



Il piattello di spinta 434 0342 10 è richiesto solamente per sistemi di rilascio già dotati di piattello di spinta.