



TSB-265 Mazda Rotary Pressure Plate Bolts

PLEASE NOTE: Two of the pressure plate bolts are shanked, as illustrated below. Because the flywheel/ pressure plate combination does not utilise dowels, it is important to ensure shanked bolts are installed in the correct holes to prevent pressure plate deflection. The holes in the flywheel will have a smooth bore at the top section before the thread and will be opposed 180°.

Shanked Bolts



Non-Shanked Bolts



LEADING BRANDS

GLUTCHPRO **GLUTCHPRO**
COMMERCIAL

