



## **TSB - LR01 Worn Clutch Fork**

Applies to: ClutchPro kit KLR24006

The Clutch fork in this model vehicle is very prone to wear.

Areas to inspect include:

- Where the fork sits on the pivot ball.
- Where the bearing pivots on the fork.

If the release fork shows any signs of fatigue the fork will need to be replaced.

Clutch Release Fork Parts Number ATFLR16

Clutch release fork suits Landrover Defender 4Cyl (both turbo and inter-cooled turbo), Range Rover 4cyl 1992-1995 inc. Turbo, Landrover and Range Rover with 380 gearbox (5 speed



CLUTCH AND FLYWHEEL SPECIALISTS











