



# CLUTCHTECH



## TSB - M101

### Mitsubishi/Hyundai

This is an important notice which relates to Clutch Pivot Ball and Release Fork Wear.

1. The clutch fork and pivot ball in this vehicle are prone to wear. Before fitting a new clutch, inspect the clutch fork, pivot ball and pivot ball seat for wear. If any wear is evident, the clutch fork and pivot ball must be replaced. Some kits are supplied with a pivot ball spacer shim. If your kit has one, you may use this under the pivot ball instead of replacing the 2 components providing they aren't damaged beyond use. Do not use a shim if the kit was not supplied with one.



2. Clean bell housing and all other gearbox components. After removal of gearbox, clean all components. Check gearbox bearing nose cone for wear. If worn, it must be replaced to avoid pedal graunch and notchy feel when new clutch is installed.

#### LEADING BRANDS

CLUTCHPRO CLUTCHPRO



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)