



# CLUTCHTECH



## TSB - TY04

This technical service bulletin relates to cover number CTY22104, CTY22104HD, CTY26121 and CTY26121HD

This aftermarket ClutchPro clutch cover has been manufactured and used by ClutchPro in many different applications. Whilst the bolt position is the same, the cover formation around the dowels is slightly different. This in no way effects the function of this clutch.



As shown in this picture to the left, the cover and dowel pins only just meet. Locate the cover and clutch disc as shown and start the bolts. This may require removing the spring washers.



The bolts need to be tightened in a "star" type formation. See picture. Please refer to manufacturers workshop manual for recommended torques.



As shown, once the clutch cover is bolted to the flywheel the dowel pins locate the clutch cover with adequate protrusion.

Note; please remember to re-fit the spring washers to the cover bolts if necessary.

**LEADING BRANDS**

