



## LuK Service Info

# Part Nr. 331 0131 19 – 310MM TDCA – 16 SPLINE

Manufacturer: FIATAGRI NEW HOLLAND  
Art.-Nr.: 331 0131 19



**TB1582**

Info: 331 0131 19 replaces / ersetzt /  
remplace / sustituye a / sostituisce 331  
0131 10



631 1072 12 = 231 0049 19 + 331 0132 16 + 500 0793 30

631 1068 19 = 231 0049 19 + 331 0132 16

631 1068 10 = 231 0049 19 + 331 0132 16 + 500 0459 00 + 500 1292 40 + 41 0026 41


631 1068 11 = 231 0049 19 + 331 0132 16 + 500 0459 00 + 500 1292 40 + 41 0025 40

631 2435 00 = 231 0049 19 + 331 0130 16 + 500 0076 11 + 500 0394 40 + 500 0284 40 +  
410 0026 41

631 1071 19 = 231 0049 19 + 331 0132 16 + 411 0012 11



331 0131 10  
OE 514 4740



331 0131 19  
OE 516 3937

Call : +44 (0) 1432 264264  
aftermarket.schaeffler.com

SCHAEFFLER  
**REP>XPERT**