

TSB-SMF01 Attention: Please read before installation and advise vehicle owner.

When fitting an Xtreme single mass flywheel replacement clutch package in certain vehicles, there may be an increase in transferred harmonic noises from the engine to the gearbox. This may present itself as a gearbox rattle. These transmitted noises in no way effect the performance of the clutch or the vehicle. Whilst every effort is made to reduce these noises by means of design, in some cases these noises are unavoidable.





Leading Brands



